

U:\000661 - Rapho\laps\Needs Area.apr View & Layout Sporting Hill 11x17 6/12/07

- Municipal Boundaries
- Wastewater Facilities
- OLDS Areas Evaluated
- Sewer Service Areas
- Floodplains
- Wetlands
- Parcels
- Bodies of Water


- WELL RESULTS**
- Wells with no Bacteria Detected and Nitrate Levels < 5 mg/l
  - Wells with no Bacteria Detected and Nitrate Levels 5-10 mg/l
  - Potential Malfunction Wells with no Bacteria Detected and Nitrate Levels > 10 mg/l
  - Wells with Bacteria Detected and Nitrate Levels < 5 mg/l
  - Wells with Bacteria Detected and Nitrate Levels 5-10 mg/l
  - Potential Malfunction Wells with Bacteria Detected and Nitrate Levels > 10 mg/l

- SANITARY SURVEY RESULTS**
- Confirmed Malfunction
  - Suspected Malfunction
  - Potential Malfunction
  - No Detected Malfunction



Rapho Township  
Lancaster County, PA

**Figure III-3**  
**ACT 537 SEWERAGE FACILITIES PLAN**  
**Sporting Hill Area**

Prepared by 

500 0 500 Feet

